

# Disability Access Audit Report 2012

## Holy Trinity Rosehill Church of England (V. A.) Primary School

ROSEHILL SITE (Nursery, FS and KS 1)				Question heading Audit date	02/10/2012	TRINITY SITE (KS 2 and Church link corridor)					
Yes	No	NA	Comments	Room / Question		Yes	No	NA	Comments		
				<b>1 - Car park/Front Entrance/Reception</b>							
				<b>All site</b>							
X				010	Can wheelchair users access the entrance gates?	X					
X				020	Is there a disabled car parking bay?	X					
X			New automatic doors fitted 2010	030	Can a wheelchair easily access the main entrance from the car park e.g. drop kerb?	X			Realigned summer 2009, level access, no kerbs		
X				040	Is the route from the car park to the main entrance well lit?	X			Post lights, timer controlled during school and church use periods		
X			Appropriate ramp to front doors.	050	Is the route from the car park to the main entrance reasonably level and free of obstructions?	X					
X				060	Is the route from the car park to the main entrance clearly signed?		X		but then the route to the car park is pretty well hidden also.		
	X		Ramp and steps, with handrails, available	070	Is the main entrance stepped?		X		There are steps but ramps also available		
X				080	Is the entrance wide enough to accommodate a wheelchair (Min. door width 775mm)?	X			Yes. Installed summer 2008. DDA compliant.		
X			Auto entry door, power assisted door mechanism fitted summer 2010	090	Are door controls easy to see and at a height suitable for wheelchair users eg handle and security system?	X					
X				100	Does the door have a vision panel at a height suitable for wheelchair users to see through?	X					
X				110	Is the lobby of sufficient size for people to clear the outer door before opening the inner door?	X					
X				120	Is Reception clearly signposted?	X			Clearly signposted, and reception desk at entrance staffed at peak times. Three steps or via lift to Office. Handrail available. Intercom at inner lobby door.		
	X			130	Is there an induction loop at Reception?		X				
				<b>2 - Circulation</b>							
				<b>All site</b>							
	X		A corridor runs three sides of the main building. At the centre of each is a 'toilet block' where the space narrows to less than 900mm.	010	Are corridors wide enough for wheelchairs users and people to pass. (Min width 900mm)?	X			Yes, but not the doors at either end.		
X				020	Are corridors free from obstruction for wheelchair users and the visually impaired.?	X					
	X		Four steps at each end of the three sides of the square route round up to entrance / main hall.	030	Are corridor floors level?		X		Three steps half way up one corridor and in the middle of the library.		
X				040	Are walls, doors and floors colour contrasted so that a visually impaired person could identify the difference?	X					
X				050	Are corridor doors accessible to a wheelchair user (min width 775mm)?	X					
	X		Original doors - 40 years old.	060	Are corridor doors glazed to allow people to see a wheelchair?	X					
	X			070	Are there suitable lifts to other floors for wheelchair users?	X					
				<b>3 - Rooms/Mean of Escape</b>							
				<b>All site</b>							
X				010	Are all appropriate room doors accessible to wheelchair users (Min width 750mm)?	X					
	X		Every classroom external door opens outwards. Each has a step down to outside. Rear hall exit ramped in August 2012. ICT suite is level access / exit. Nursery has level access / exit.	020	Are all designated fire exit routes and exit doors suitable for wheelchair egress?		X		Some / Many have a step down outside.		
		X	All doors are fire doors.	030	Are all other external exits suitable for wheelchair access/egress?		X		Many / Most have a step down outside.		
		X		040	Where there is wheelchair access to an upper floor do you have procedures in place for evacuation?			X			
		X		050	Is there an evacuation chair on each upper floor where wheelchair access is available?			X			
	X			060	Does the main hall (s) have an induction loop?		X				
				<b>4 - Toilets/Washrooms</b>							
				<b>All site</b>							
X	X		In Nursery, the staff toilet can be used. In the main Rosehill building there is no modified provision.	010	Is there suitable toilet provision for disabled users?	X			However, access from all parts of the building is not easy.		
	X	X	No in Nursery, not applicable in Rosehill site	020	Does the toilet have an alarm ?	X			see above		
X		X	Yes in Nursery, not applicable in Rosehill site	030	Is there a handrail fitted within the disabled WC?	X			see above		
	X	X	No in Nursery, not applicable in Rosehill site	040	Are urinals and wash basins colour contrasted to the walls?	X			see above		
				<b>5 - Playground</b>							
				<b>All site</b>							
	X		See comments about fire doors etc. All accessible from off-site but not classroom to playground.	010	Are all playgrounds accessible to wheelchair users?		X		From outside premises yes, from all doors, no. See 'means of escape'.		
				<b>6 - Specialist Area</b>							
				<b>All site</b>							
	X		ICT suite, Food tech areas are not altered to suit.	010	In specialist classrooms eg woodwork, is there a lowered workstation suitable for wheelchair users?		X		ICT suite, Food tech areas are not altered to suit.		

\\asset2\el\Program Files\TribalEnterprise\Report\Audit\Answer.rpt